


Steps:

1. Wire stepper drive:

VDC+ to +24V
 VDC- to ground
 A+ to motor cable RED
 A- to motor cable WHITE
 B+ to motor cable GREEN
 B- to motor cable BLACK

STEP+ to +24V
 STEP- to PLC Y0
 DIR+ to +24V
 DIR- to PLC Y1

PLC output 1C to ground
 PLC V+ to 24V
 PLC V- to ground



2. Set stepper drive to proper motor current (see data sheet)
3. Set stepper drive to 2000 steps/rev resolution (see data sheet)
4. Connect plc to laptop, run Domore Designer, and connect to PLC.
5. Go to PLC -> System Configuration, BRX Local I/O, then click on High Speed I/O.
6. Under Axis/Pulse Outputs, set Axis 1 to pulse output, step/direction, Y0 to STEP, Y1 to DIR
7. Make a ladder diagram with three stages. In S0, have a rung with \$on and AXCONFIG box.
8. Configure AXCONFIG to Axis 1, rotary, rotary range to 1001 steps (0-1000), and jump to S1 on success.
9. In S1, put a rung with \$on and AXPOSTRAP box.
10. Configure AXPOSTRAP with Axis 1, rotary, absolute CW, target 1000 pulses, jump to S2 on success.
11. In S2, put a rung with \$on and AXPOSSCRV box.
12. Configure AXPOSSCRV with Axis 1, rotary, absolute CCW, target 0 pulses jump to S1 on success.
13. Write PLC and run. Motor should rotate 1/2 rev each way. Experiment with changing acceleration and velocity parameters. What is the highest pulse rate before stalling?