


Steps to using the CTRIO module to control step motors:

1. Wire the CTRIO to step motor amplifier
  - a. Y0 to STEP-
  - b. Y1 to DIR-
  - c. STEP+ to a 2200ohm resistor which connects to +24V
  - d. DIR+ to another 2200ohm resistor which connects to +24V
2. Run CTRIO WorkBench - Directsoft PLC
  - a. Do "Config I/O", set to Pulse Step/Direction
  - b. Do "I/O Map"
    - 1) Check "Enable Write to PLC"
    - 2) Use V2000 as address for inputs
    - 3) Check "Enable Read from PLC"
    - 4) Use V2030 as address for outputs
  - c. Create "Pulse Profiles"
    - 1) Add a profile
      - usually use trapazoidal or S-curve
      - set up appropriate parameters for acceleration, velocity, and number of pulses (keeping in mind steps/rev of motor amplifier)
      - name your profile
    - 2) Add additional profiles as needed
  - d. Click "Write Module" (if "Write Module" is grayed out, click "Goto PROGRAM")
  - e. Click "Goto Run"
3. Setup your PLC logic
  - a. Write "load table" command (K10) to V2040
  - b. Load profile table number into V2041
  - c. Be sure direction bit (B2056.4) is 0 or 1 as appropriate
  - d. Set output enable bit (B2056.0) to 1. Your motor should turn.
  - e. Wait until output active bit (B2022.4) goes inactive (motion complete)



Create PLC logic and step motor motion profile to move when switch0 (X120) is turned on. If switch1 (X121) is off, then the move should be 30 degrees. If X121 is on, then the move should be 120 degrees. Use switch2 (X122) to set the direction of motion.