



Machinability

- The enemies:
 - heat
 - vibration





Form Errors

- Deflection of cutter (in end milling) or work (in turning) causes form error




Vibration (chatter)



Dynamic chip thickness


Vibration



Static chip thickness


- Vibration at present tooth period

+ Vibration at previous tooth period






Vibration


- Choose highest spindle RPM
- Tune tool length to stay in a stable lobe at top spindle RPM



Vibration




Process

- Rigidity:
 - use shortest tool and tool holder
 - deflection of tool or work causes *form* error
 - keep workpiece firmly clamped and supported
 - avoid speed/feed/depth combos that chatter
 - Heat:
 - use coated tools when heat is a problem
 - keep chips cleared (liquid or air coolant)
 - hard chips get harder
 - soft chips stick to tool
 - don't go too fast OR too slow
 - Chip load:
 - keep volume removed constant!
 - especially watch tool entry, exit, corners
- 
- A detailed technical drawing of a machine tool assembly, likely a lathe or similar turning machine. The drawing shows various components such as the headstock, tailstock, bed, and carriage, with numerous numbered callouts (e.g., 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100) pointing to specific parts. The drawing is a cross-sectional view showing the internal structure and mechanical linkages of the machine.

Doing Vertical Milling


- Select stock
 - material, dimension
- Select workholding
 - usually vice or strap clamps
- Select tools & create toolpath
 - FeatureCAM for CNC, by hand for manual
- Set work and tool offsets (for CNC)
- Determine feeds, speeds, and cutting depth
 - FeatureCAM helps with this for CNC



Vertical Milling



Coordinate System




Work Offsets

- Work Offsets
 - G54-G59
 - G54 X & Y aligned with vice step jaw left front
 - Set G54 Z to height of top of work (type number, press F1)



Offsets



Setting Work Offset

WORK ZERO OFFSET

G CODE	X	Y	Z	
G 52	0.	0.	0.	
G 54	-18.4871	-8.1975	6.4515	
G 55	-18.8788	-8.5888	0.	
G 56	-22.6688	-6.8888	0.	
G 57	-16.3988	-2.6288	6.8888	
G 58	-12.4185	-8.8782	5.8248	
G 59	-18.4871	-8.8782	5.2285	
G154 P1	0.	0.	0.	(G118)
G154 P2	0.	0.	0.	(G111)
G154 P3	0.	0.	0.	(G112)
G154 P4	0.	0.	0.	(G113)
G154 P5	0.	0.	0.	(G114)
G154 P6	0.	0.	0.	(G115)
G154 P7	0.	0.	0.	(G116)
G154 P8	0.	0.	0.	(G117)
G154 P9	0.	0.	0.	(G118)
G154 P10	0.	0.	0.	(G119)
G154 P11	0.	0.	0.	(G120)
G154 P12	0.	0.	0.	(G121)
G154 P13	0.	0.	0.	(G122)
G154 P14	0.	0.	0.	(G123)
G154 P15	0.	0.	0.	(G124)
G154 P16	0.	0.	0.	(G125)
G154 P17	0.	0.	0.	(G126)

Z POSITION : -5.8343 WRITE ADD/P1 SET/OFFSET TOGGLE


RAPID 58X
JOGGING Y AXIS HANDLE .0001

Tool Offsets

- Select tool #
- Jog until touch
- Press "Tool Offset Measure"
- Subtract 2.000" (-2.0 Enter)

TOOL	POSITION	GEOMETRY	WEAR	GEOMETRY	WEAR	FLUTES
1		-16.1442	0.	0.1250	0.	2
2		-16.7966	0.	0.1250	0.	2
3		-16.7883	0.	0.1250	0.	2
4		-12.2747	0.	0.1000	0.	2
5		-13.9795	0.	0.3750	0.	4
6		-16.2011	0.	0.2500	0.	2
7		-14.4071	0.	0.3125	0.	2
8		-14.4289	0.	0.1250	0.	2
9		-16.9389	0.	0.0625	0.	2
10		-17.0816	0.	0.0625	0.	2
11		0.	0.	0.	0.	2
12		0.	0.	0.	0.	2
13		0.	0.	0.	0.	2
14		0.	0.	0.	0.	2
15		0.	0.	0.	0.	2
16		0.	0.	0.	0.	2
17		0.	0.	0.	0.	2
18		0.	0.	0.	0.	2
19		0.	0.	0.	0.	2
20		0.	0.	0.	0.	2

Z POSITION : -14.1442 WRITE ADD/F1 SET/OFFSET TOGGLE



CNC Programming

- Example CNC program - bores a center hole and drills bolt circle
- Haas manual at:
k:\class\enegr\480\haas\usermanual.pdf





```
%
000100
(Maxon motor bolt circle program);
(center hole 0.256R);
T3 M06; (Get tool T3 from toolchanger);
G00 G90 G54 X0.74 Y0.63; (Move to 0.74,0.63 in G54 coord sys);
S1100 M03; (Set spindle speed at 1100 RPM and start CW);
G43 H03 Z0.3 M08; (Compensate for tool length, Set return height);
G01 Z0 F10; (drop to surface);
G12 G91 Z0.05 I0.1 K0.256 Q0.01 L3 D03 F1.0; (Bore center hole);
G00 G90 Z1. M09; (return to 1" above surface, turn off coolant);

(bolt circle - 0.374R, peck 0.05);
G70 I0.374 J60.0 L6; (0.374R, 60deg, 6 holes);
T1 M06; (Get tool T1);
G00 G90 G54 X0.74 Y0.63; (Move to 0.5,0.5 in G54 coord sys);
S1050 M03; (Set spindle to 1050 RPM);
G43 H01 Z1. M08; (Compensate for tool len, set ret height, coolant on);
G82 G98 Z-0.05 P1. R0.1 F5.; (Execute drill cycle for each hole);
G00 G80 Z1. M09; (Cancel cycle, turn off coolant);
G28 G91 Z0 M05; (Return home, turn off spindle);
M30; (End of program);|
```

Loading CNC Program from Floppy

- Name program with 8 or fewer letters
- Copy to a: drive
- Put in Haas
 - press List Prog, type in name, press F3



Mill/Turn Video

