


Chip Forming Operations



- Drilling
 - Drill press
 - Mill
 - Lathe
- Turning
 - Lathe
- Milling
 - Mill

Turning

- Rotating work, fixed tool






Turning



<http://easylink.playstream.com/omniturn/pillcase.aspx>

Turning


- Collets
- Chucks
- Centers




Machinability

- The enemies:
 - heat
 - vibration

Vibration (chatter)




Vibration




Vibration

- For Max Material Removal Rate:
 - Choose highest spindle RPM
 - Tune tool length to stay in a stable lobe at top spindle RPM



Vibration

Stability Lobes for Bull Nose Cutter and Al7075




Process

- Rigidity:
 - use shortest tool and tool holder
 - deflection of tool or work causes *form* error
 - keep workpiece firmly clamped and supported
 - avoid speed/feed/depth combos that chatter
- Heat:
 - use coated tools when heat is a problem
 - keep chips cleared (liquid or air coolant)
 - hard chips get harder
 - soft chips stick to tool
 - don't go too fast OR too slow
- Chip load:
 - keep volume removed constant!
 - especially watch tool entry, exit, corners

Doing Vertical Milling

- Select stock
 - material, dimension
- Select workholding
 - usually vice or strap clamps
- Select tools & create toolpath
 - FeatureCAM for CNC, by hand for manual
- Set work and tool offsets (for CNC)
- Determine feeds, speeds, and cutting depth
 - FeatureCAM helps with this for CNC

Vertical Milling



Coordinate System




Work Offsets

- Work Offsets
 - G54-G59
 - G54 X & Y aligned with vice step jaw left front
 - Set G54 Z to height of top of work (type number, press F1)



Offsets



Setting Work Offset


WORK ZERO OFFSET			
G CODE	X	Y	Z
G 52	0.	0.	0.
G 54	-18.4871	-8.1975	6.4515
G 55	-18.8788	-8.5888	0.
G 56	-22.6688	-6.8888	0.
G 57	-16.3988	-2.6288	6.8888
G 58	-12.4185	-8.8782	5.8248
G 59	-18.4871	-8.8782	5.2285
G154 P1	0.	0.	0. (G118)
G154 P2	0.	0.	0. (G111)
G154 P3	0.	0.	0. (G112)
G154 P4	0.	0.	0. (G113)
G154 P5	0.	0.	0. (G114)
G154 P6	0.	0.	0. (G115)
G154 P7	0.	0.	0. (G116)
G154 P8	0.	0.	0. (G117)
G154 P9	0.	0.	0. (G118)
G154 P10	0.	0.	0. (G119)
G154 P11	0.	0.	0. (G120)
G154 P12	0.	0.	0. (G121)
G154 P13	0.	0.	0. (G122)
G154 P14	0.	0.	0. (G123)
G154 P15	0.	0.	0. (G124)
G154 P16	0.	0.	0. (G125)
G154 P17	0.	0.	0. (G126)
Z POSITION : -5.8343 WRITE ADD/F1 SET/OFSET TOGGLE			
RAPID 58%			
JOGGING Y AXIS HANDLE .0001			
-8.1975			

Tool Offsets

- Select tool #
- Jog until touch
- Press "Tool Offset Measure"
- Subtract 2.000" (-2.0 Enter)

TOOL	POSITION	GEOMETRY	WEAR	GEOMETRY	WEAR	FLUTES
1		-16.1442	0.	0.1250	0.	2
2		-16.7966	0.	0.1250	0.	2
3		-16.7883	0.	0.1250	0.	2
4		-12.2747	0.	0.1000	0.	2
5		-13.9795	0.	0.3750	0.	4
6		-16.2011	0.	0.2500	0.	2
7		-14.4871	0.	0.3125	0.	2
8		-14.4289	0.	0.1250	0.	2
9		-16.9389	0.	0.0625	0.	2
10		-17.0816	0.	0.0625	0.	2
11		0.	0.	0.	0.	2
12		0.	0.	0.	0.	2
13		0.	0.	0.	0.	2
14		0.	0.	0.	0.	2
15		0.	0.	0.	0.	2
16		0.	0.	0.	0.	2
17		0.	0.	0.	0.	2
18		0.	0.	0.	0.	2
19		0.	0.	0.	0.	2
20		0.	0.	0.	0.	2

Z POSITION : -14.1442 WRITE ADD/F1 SET/OFFSET TOGGLE



CNC Programming

- Example CNC program - bores a center hole and drills bolt circle
- Haas manual at:
k:\class\enegr\480\haas\usermanual.pdf

```
%
000100
(Maxon motor bolt circle program);
(center hole 0.256R);
T3 M06; (Get tool T3 from toolchanger);
G00 G90 G54 X0.74 Y0.63; (Move to 0.74,0.63 in G54 coord sys);
S1100 M03; (Set spindle speed at 1100 RPM and start CW);
G43 H03 Z0.3 M08; (Compensate for tool length, Set return height);
G01 Z0 F10; (drop to surface);
G12 G91 Z0.05 I0.1 K0.256 Q0.01 L3 D03 F1.0; (Bore center hole);
G00 G90 Z1. M09; (return to 1" above surface, turn off coolant);

(bolt circle - 0.374R, peck 0.05);
G70 I0.374 J60.0 L6; (0.374R, 60deg, 6 holes);
T1 M06; (Get tool T1);
G00 G90 G54 X0.74 Y0.63; (Move to 0.5,0.5 in G54 coord sys);
S1050 M03; (Set spindle to 1050 RPM);
G43 H01 Z1. M08; (Compensate for tool len, set ret height, coolant on);
G82 G98 Z-0.05 P1. R0.1 F5.; (Execute drill cycle for each hole);
G00 G80 Z1. M09; (Cancel cycle, turn off coolant);
G28 G91 Z0 M05; (Return home, turn off spindle);
M30; (End of program);
```

Loading CNC Program from Floppy

- Name program with 8 or fewer letters
- Copy to a: drive
- Put in Haas
 - press List Prog, type in name, press F3



```
PROGRAM (LIST PROG) 000999 1000000
000000
000001 (p:\Pend\seq0001.ncl.1)
000002 (p:\Pend\step2.ncl.5)
000101 (p:\Senior Project\Prototype3\sa)
000102 (p:\Senior Project\Prototype3\sa)
000111 (p:\Senior Project\Prototype3\h2)
000112 (p:\Senior Project\Prototype3\h2)
000113 (p:\Senior Project\Prototype3\h2)
000200 (p:\Senior Project\Prototype3\ho)
000300 (p:\Senior Project\Prototype3\ho)
000314 (p:\Senior Project\Prototype3\h2)
000400 (p:\Senior Project\Prototype3\h2)
000500 (p:\Senior Project\Prototype3\ca)
000555
001027 (p:\Senior Project\Prototype3\h2)
001103 (p:\Pend\step3.ncl.7)
001117 (p:\cnc.ncl.2)
001238 (G83 Peck Drill, 2-Hole)
001557 (p:\cal.ncl.1)
002346 (C:\Documents and Settings\David)
004324 (C:\Documents and Settings\David)
005656 (p:\manu_lab\pcd2.ncl.2)
005768 (p:\manu_lab\platecdrill.ncl.2)
006968 (p:\Senior Project\Prototype3\sa)
006969 (p:\Senior Project\Prototype3\sa)
30 PROGRAMS 69% FREE (706812 BYTES)
ALL TO SEND, RECV, ERASE F1 TO DUP PROG
F2 DISK WR, F3 DISK RD, F4 DIR RD
RAPID 50%
SPHERE1.NC
```

Mil I /Turn Video

