

# Generating Motion

---

- Moving a part adds no value (except in packaging)
- Moving a tool adds no value unless work is done on part.
- So, we want to avoid moving parts or tools any more than necessary
  - One metal machining batch factor: 95% of a parts time is spent moving or waiting, 5% of time is on tool, of which only 30% is spent cutting.

# Linear Motion

---

- Linear translation is most common motion
- Linear movement can be caused by:
  - Pneumatic or hydraulic cylinders
  - Rotary motion converted to linear
  - Vibratory systems
  - Electric solenoids
  - Linear electric motors
  - Piezoelectric actuators

# Pneumatic Systems

---

- Pneumatic power very popular in industry
  - High force, economical linear motion
  - Non-flammable, compressible, storable medium
  - Compact, low heat production actuators
- Pneumatics best suited to discrete motion (not proportional)


# Pneumatic Systems

---

- Ideal Gas Law:  $PV = mRT$
- Boyle's Law:  $P_1V_1 = P_2V_2$


# Pneumatic System Layout

---




# Air Preparation

---




# Single-Acting Cylinder

---




# Single-Acting Cylinder

---



# Double-Acting Cylinder

---





# Pneumatic Cylinder Mounting

---

- Off-axis loading must be prevented!
- Pivoting mounts can eliminate axial loading:
  - Clevis mount
  - Trunnion mount
  - Universal joints
- Shaft may rotate unless antirotation model is used


# Trunnion Mount

---



# Pneumatic Twin Cylinder


---






# Pneumatic Bellows

---

Single Fold Bellows Cylinder




Double Fold Bellows Cylinder




# Pneumatic Bel lows

---




# Pneumatic Rotary Actuators

---



# Pneumatic Rotary Actuators


---



# Pneumatic Schematics

---


*Not actuated*



# Pneumatic Schematics


---

*Actuated*



# Electric Solenoids



---



$$\text{Force} \propto \text{stroke}^{-1}$$

# Electric Rotary Actuator (solenoid)

---



# Electric Rotary Actuators (motors)

---

- DC motors
- AC motors
  - stepper (2-phase synchronous)
  - brushless (3-phase synchronous)
  - induction

# Step Motors

---

Figure 2. "One phase on" stepping sequence for two phase motor.






Figure 3. "Two phase on" stepping sequence for two phase motor.



# Step Motors

---


*Fig. 1.4 Simple 12 step/rev hybrid motor*



# Step Motor

## 12 step/rev, 1 phase on






---



# Step Motor

## 12 step/rev, 2 phase on






---



# Step Motor

## 12 step/rev, hal f-stepping


---



# Step Motors

---

*Fig. 1.13 Motor lead configurations*




# Selecting Step Motors

---

- Torque
- Speed
- Current
- Lead configuration


# Torque/Speed

---



# Series/Parallel Wiring

---



# Step Motor Drives

---

- Resolution (full, half, microstepping)
- Current Limit (resistor or digital)
- AC powered or DC powered
- Pulse/Direction or Indexing

# Resolution

---

- Full step/Half step
- Microstepping
  - x2,x4,x5,x8,x10,x16,x25,x32,x50,x64,x125,x128,x250,x256 common choices
- Max step frequency
  - PLC: 7kHz pulse rate => 2100 RPM at x1, 8.2RPM at x256 (1.8deg motor)
  - Compumotor 6104: 2MHz pulse rate => 2300RPM at x256
- Resonance problems