

Lathe Coordinate System

MORI SEIKI
THE MACHINE TOOL COMPANY

COORDINATES


2. X-Axis and Z-Axis

Basic model of NC lathe has two numerically controlled axes, called X-axis and Z-axis.

X-axis The axis along which the cross slide moves.


Z-axis The axis along which the carriage moves.

The direction of an axis is determined by the positive (plus) and negative (minus) signs.



Workpiece Zero Point


- Coordinate system zero point is
 - centerline of spindle (X)
 - with normal spindle rotation, machining is in +X
 - finish face of part (Z)
 - Machining is in $-Z$ if $Z=0$ is finish face
 - Second ops may use back side of part as $Z=0$
- X dimensions are *diameter*, not radius



WORKPIECE ZERO POINT

a) Chuck-work


X-axis: Diametric commands



WORKPIECE ZERO POINT


b) Center-work

X-axis: Diametric commands




4. Tool Command Point


a) O.D./Face Turning




b) O.D. Grooving




c) O.D. Threading



d) I.D. Turning




e) I.D. Grooving



Example

Let's find out the dimensional data (actually, coordinate values) of five points (① to ⑤) in the drawing below.




(Fig. 1-6)

- O _____
- ① X_____ Z_____
- ② X_____ Z_____
- ③ X_____ Z_____
- ④ X_____ Z_____
- ⑤ X_____ Z_____

M30

Dimensions (coordinate values) of point (1) to point (5) are indicated below.

Point	Dimension		Program Command	
	Diametric Direction	Longitudinal Direction	Diametric Direction	Longitudinal Direction
(1)	40 mm	0 mm	X40.0	Z 0
(2)	50 mm	-5 mm	X50.0	Z-5.0
(3)	50 mm	-50 mm	X50.0	Z-50.0
(4)	80 mm	-50 mm	X80.0	Z-50.0
(5)	100 mm	-60 mm	X100.0	Z-60.0




Keep in mind!
Double the values in the X-axis (diametric) direction.

6. Dimensions in Programming

6.1 Absolute Programming

Points (1) to (4) in Fig. 1-6 may be expressed as shown below.

(1) X40000	Z0		X40.0	Z0
(2) X50000	Z-5000		X50.0	Z-5.0
(3) X50000	Z-50000		X50.0	Z-50.0
(4) X80000	Z-50000		X80.0	Z-50.0
(5) X100000	Z-60000		X100.0	Z-60.0

That is, values as indicated below are used to express X and Z values.

X: Diameter of the workpiece (in reference to X0)
Z: Distance from the workpiece zero point (Z0)

The sign that immediately follows X or Z shows the area where the point lies. If the sign is "+", it is usually omitted.
 If the same coordinate value continues, the second and later appearance may be omitted.

6.2 Incremental Programming

In incremental programming, addresses U (in diameter) and W are used to express dimensions in the X-axis and Z-axis directions, respectively, to clearly identify it from absolute programming. In this programming method, the plus sign (omitted) and the minus sign indicate the direction in which the tool (command point) moves. The numerical value that follows the sign indicates the distance.


If you use the incremental commands to express point (1) to point (5) of the sample workpiece in Fig. 1-6, the commands are as shown below.

Point (1)	X40.0	Z0
Point (2)	U10.0	W-5.0
Point (3)		W-45.0
Point (4)	U30.0	
Point (5)	U20.0	W-10.0

<Use of Incremental Programming>

This programming method is usually used in retracting (moving away) the tool from the cut surface (O.D., I.D., end face).

7. Cutting Conditions



7.1 How to Determine Cutting Conditions

- (1) Cutting speed (spindle speed) : Material and shape of workpiece
Insert material (hardness in high temperature and wear resistivity)
- (2) Cutting feedrate : Rigidity of the machine and tools
Nose radius of insert ($F_{max.} \leq Nr/2$)
Chip breaker shape
Surface finish specified in the drawing → Nose radius
- (3) Depth of cut : Rigidity of the machine and tools
Main motor output
Insert thickness ($D_{max} \leq$ Insert thickness)
Cutting edge length of insert
Chip breaker shape
- (4) Workpiece holding conditions : Workpiece holding status and method
Workpiece shape
Size and balance of jaws
Chucking pressure
Tailstock spindle thrust force

Major Five Functions That Control NC Lathe

1. **G Function: Preparatory function**

Commands related to X-/Z-axis feed control/G00, G01, G02

2. **M Function: Miscellaneous function**

ON/OFF commands output from the CNC to the NC lathe/M00, M03, M08

3. **T Function: Tool selection function**

Calling the tool to be used/T0101 (4-digit T code)

4. **S Function: Spindle speed (min^{-1}) and cutting speed (m/min)**

Spindle speed command/S500 (= 500 min^{-1})

Cutting speed command/S200 (= 200 m/min)

5. **F Function: Feedrate command (mm/rev)**

Tool feedrate command/F0.3 (= 0.3 mm/rev)

BASIC PATTERNS OF PROGRAM (1)

$\bar{O}1$
N1
G50S2000
G00T0101
G962S00M03




G00U1.0Z10.0
X300.0Z150.0
M01
M30;

Program number (O1~O9999)

Program name

Must be specified at the beginning
of all programs.

In the storage area



NC reset & rewind

BASIC PATTERNS OF PROGRAM (2)

O1
N1
G50S2000
G00T0101
G96S200M03

⋮

G00U1.0Z10.0
X300.0Z150.0
M01
;

Sequence number (to be specified at the beginning of a part program)

Usually, a sequence number is specified at the beginning of individual machining processes to identify the processes.

- Rough O.D. turning N1
- Rough I.D. turning N2
- Finish O.D. turning N3
- N4
- N5
- Thread cutting N6



BASIC PATTERNS OF PROGRAM (3)

```
O1  
N1  
G50 S2000
```

```
G00 T0101
```

```
G96S200M03
```

.....

```
G00U1.0Z10.0
```

```
X300.0Z150.0
```

```
M01
```

```
;
```

The command specifying
the allowable maximum
spindle speed



BASIC PATTERNS OF PROGRAM (4)

```
O1  
N1  
G50S2000  
G00 T0101  
G96S200M03  
.....  
  
G00U1.0Z10.0  
X300.0Z150.0  
M01
```

The command
specifying the tool
number and the tool
position offset number



BASIC PATTERNS OF PROGRAM (5)

O1

N1

G50S2000

G00T0101

G96

S200M03

The command specifying the cutting speed, spindle rotation in the normal direction and spindle revolving speed

G00U1.0Z10.0

X300.0Z150.0

M01



BASIC PATTERNS OF PROGRAM (6)

O1

N1

G50S2000

G00T0101

G96S200M03

.....

G00U1.0Z10.0

X300.0Z150.0

M01

;

Moving the tool away
from the workpiece after
finishing the machining



BASIC PATTERNS OF PROGRAM (7)

O1

N1

G50S2000

G00T0101

G96S200M03




G00U1.0Z10.0

X300.0Z150.0

M01

;



Moving the tool to the
position where turret
rotation is possible
Optional stop



THE LAST BLOCK

$\bar{O}1$
N1
G50S2000
G00T0101
G96S200M03
⋮
G00U1.0Z10.0
X300.0Z150.0
M01
⋮
M30

← NC reset and rewind



THANK YOU for your careful
attention to my lecture.



This ends the explanation of
programming.

*I hope all of
you enjoyed
to understand
programming
basics.*



Lathe Tooling

- Turning
- Boring
- OD Grooving
- ID Grooving
- Face Grooving
- OD Threading
- ID Threading




CNC Lathe Programming

1 block


```
N 00000 G 00 X00.0 Z000.0 M 00 S 00 T 00 ;
```

Sequence number Preparatory function Dimension word Miscellaneous function Spindle function Tool function

End of block




G-Codes for Turning




G00	Rapid positioning
G01	Linear interpolation (feeding)
G02	CW Circular interpolation
G03	CCW Circular interpolation
G04	Dwell
G20	Inch system
G21	Metric system
G28	Return to reference point
G50	Limit spindle speed

G-Codes for Turning



G54	Select work coord system #1
G70	Finishing cycle
G71	Roughing cycle
G72	Facing cycle
G76	Threading cycle
G96	Constant <i>surface</i> speed mode
G97	Constant <i>spindle</i> speed mode
G98	Feed per minute mode
G99	Feed per revolution mode

M-Codes for Turning



A technical drawing of a lathe machine is overlaid on the table. The drawing shows various components of the machine, including the headstock, tailstock, bed, and carriage, with numerous numbered callouts (e.g., 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100) pointing to specific parts.

M00	Program Stop
M01	Opt. Program Stop (panel controlled)
M03	Start spindle (normal rotation)
M04	Start spindle (reverse rotation)
M05	Stop spindle
M08	Start coolant
M09	Stop coolant
M10	Close chuck
M11	Open chuck
M30	Program end