


# Doing Vertical Milling

---

- Select stock
  - material, dimension
- Select workholding
  - usually vice or strap clamps
- Select tools & create toolpath
  - FeatureCAM for CNC, by hand for manual
- Set work and tool offsets (for CNC)
- Determine feeds, speeds, and cutting depth
  - FeatureCAM helps with this for CNC




# Vertical Milling

---



# Coordinate System

---






# Work Offsets

---

- Work Offsets
  - G54-G59
  - G54 X & Y aligned with vice step jaw left front
  - Set G54 Z to height of top of work (type number, press F1)



# Offsets



# Setting Work Offset


WORK ZERO OFFSET

G CODE	X	Y	Z	
G 52	0.	0.	0.	
G 54	-18.4871	-8.1975	6.4515	
G 55	-18.8788	-8.5888	0.	
G 56	-22.6688	-6.8888	0.	
G 57	-16.3988	-2.6288	6.8888	
G 58	-12.4185	-8.8782	5.8248	
G 59	-18.4871	-8.8782	5.2285	
G154 P1	0.	0.	0.	(G118)
G154 P2	0.	0.	0.	(G111)
G154 P3	0.	0.	0.	(G112)
G154 P4	0.	0.	0.	(G113)
G154 P5	0.	0.	0.	(G114)
G154 P6	0.	0.	0.	(G115)
G154 P7	0.	0.	0.	(G116)
G154 P8	0.	0.	0.	(G117)
G154 P9	0.	0.	0.	(G118)
G154 P10	0.	0.	0.	(G119)
G154 P11	0.	0.	0.	(G120)
G154 P12	0.	0.	0.	(G121)
G154 P13	0.	0.	0.	(G122)
G154 P14	0.	0.	0.	(G123)
G154 P15	0.	0.	0.	(G124)
G154 P16	0.	0.	0.	(G125)
G154 P17	0.	0.	0.	(G126)

Z POSITION : -5.8343 WRITE ADD/F1 SET/OFSET TOGGLE

RAPID 58X  
JOGGING Y AXIS HANDLE .0001

0675






# Tool Offsets

- Select tool #
- Jog until touch
- Press "Tool Offset Measure"
- Subtract 2.000" (-2.0 Enter)


TOOL	POSITION	GEOMETRY	WEAR	GEOMETRY	WEAR	FLUTES
1		-16.1442	0.	0.1250	0.	2
2		-16.7966	0.	0.1250	0.	2
3		-16.7883	0.	0.1250	0.	2
4		-12.2747	0.	0.1000	0.	2
5		-13.9795	0.	0.3750	0.	4
6		-16.2011	0.	0.2500	0.	2
7		-14.4871	0.	0.3125	0.	2
8		-14.4289	0.	0.1250	0.	2
9		-16.9389	0.	0.0625	0.	2
10		-17.0816	0.	0.0625	0.	2
11		0.	0.	0.	0.	2
12		0.	0.	0.	0.	2
13		0.	0.	0.	0.	2
14		0.	0.	0.	0.	2
15		0.	0.	0.	0.	2
16		0.	0.	0.	0.	2
17		0.	0.	0.	0.	2
18		0.	0.	0.	0.	2
19		0.	0.	0.	0.	2
20		0.	0.	0.	0.	2

Z POSITION : -14.1442 WRITE ADD/F1 SET/OFFSET TOGGLE




# Machinability

- The enemies:
  - heat
  - vibration






# Vibration (chatter)




# Vibration



Static chip  
thickness


- Vibration at present  
tooth period

+ Vibration at previous  
tooth period



# Vibration


- For Max Material Removal Rate:
  - Choose highest spindle RPM
  - Tune tool length to stay in a stable lobe at top spindle RPM





# Vibration

## Stability Lobes for Bull Nose Cutter and Al7075



# Process

---

- Rigidity:
  - use shortest tool and tool holder
    - deflection of tool or work causes *form* error
  - keep workpiece firmly clamped and supported
  - avoid speed/feed/depth combos that chatter
- Heat:
  - use coated tools when heat is a problem
  - keep chips cleared (liquid or air coolant)
    - hard chips get harder
    - soft chips stick to tool
  - don't go too fast OR too slow
- Chip load:
  - keep volume removed constant!
  - especially watch tool entry, exit, corners

