


# DOING VERTICAL MILLING

---

- Select stock
  - material, dimension
- Select workholding
  - usually vice or strap clamps
- Select tools & create toolpath
  - FeatureCAM, Pro/E or hand-edited G-code for CNC, by hand for manual
- Set work and tool offsets (for CNC)
- Determine feeds, speeds, and cutting depth
  - FeatureCAM helps with this for CNC




# VERTICAL MILLING

---



# COORDINATE SYSTEM

---




# WORK OFFSETS

- Work Offsets
  - G54-G59
  - G54 X & Y aligned with vice jaw left front
  - Set G54 Z to height of top of work (type number, press F1)





# OFFSETS



# SETTING WORK OFFSET

```
WORK ZERO OFFSET
G CODE      X           Y           Z
G 52        0.         0.         0.
G 54        -18.4871   -8.1975   6.4515
G 55        -18.8788   -8.5888   0.
G 56        -22.6688   -6.8888   0.
G 57        -16.3988   -2.6288   6.8888
G 58        -12.4185   -8.8782   5.8248
G 59        -18.4871   -8.8782   5.2285
G154 P1     0.         0.         0.      (G118)
G154 P2     0.         0.         0.      (G111)
G154 P3     0.         0.         0.      (G112)
G154 P4     0.         0.         0.      (G113)
G154 P5     0.         0.         0.      (G114)
G154 P6     0.         0.         0.      (G115)
G154 P7     0.         0.         0.      (G116)
G154 P8     0.         0.         0.      (G117)
G154 P9     0.         0.         0.      (G118)
G154 P10    0.         0.         0.      (G119)
G154 P11    0.         0.         0.      (G120)
G154 P12    0.         0.         0.      (G121)
G154 P13    0.         0.         0.      (G122)
G154 P14    0.         0.         0.      (G123)
G154 P15    0.         0.         0.      (G124)
G154 P16    0.         0.         0.      (G125)
G154 P17    0.         0.         0.      (G126)
Z POSITION :  -5.8343  WRITE ADD/F1 SET/OFSET TOGGLE
```

RAPID 58X  
JOGGING Y AXIS HANDLE .0001




# TOOL OFFSETS

- Select tool #
- Jog until touch
- Press “Tool Offset Measure”
- Subtract 2.000” (-2.0 Enter)


TOOL	POSITION	GEOMETRY	WEAR	GEOMETRY	WEAR	FLUTES
1		-16.1442	0.	0.1250	0.	2
2		-16.7966	0.	0.1250	0.	2
3		-16.7883	0.	0.1250	0.	2
4		-12.2747	0.	0.1000	0.	2
5		-13.9795	0.	0.3750	0.	4
6		-16.2011	0.	0.2500	0.	2
7		-14.4871	0.	0.3125	0.	2
8		-14.4289	0.	0.1250	0.	2
9		-16.9389	0.	0.0625	0.	2
10		-17.0816	0.	0.0625	0.	2
11		0.	0.	0.	0.	2
12		0.	0.	0.	0.	2
13		0.	0.	0.	0.	2
14		0.	0.	0.	0.	2
15		0.	0.	0.	0.	2
16		0.	0.	0.	0.	2
17		0.	0.	0.	0.	2
18		0.	0.	0.	0.	2
19		0.	0.	0.	0.	2
20		0.	0.	0.	0.	2

2 POSITION : -14.1442 WRITE ADD/F1 SET/OFFSET TOGGLE



# PROCESS

- Rigidity:
  - use shortest tool and tool holder
    - deflection of tool or work causes form error
  - keep workpiece firmly clamped and supported
  - avoid speed/feed/depth combos that chatter
- Heat:
  - use carbide tools when heat is a problem
  - keep chips cleared (liquid or air coolant)
    - hard chips get harder
    - soft chips stick to tool
  - don't go too fast OR too slow
- Chip load:
  - keep volume removed constant!
  - especially watch tool entry, exit, corners




# SETTING FEEDS & SPEEDS

Aluminum (6061, 2024, 7075)				
SFM	Chipload Per Tooth			
<u>2, 3, &amp; 4 Flute</u>	<u>up to .125 dia.</u>	<u>.125-.250 dia.</u>	<u>.250-.500 dia.</u>	<u>.500-1.0 dia.</u>
300-500	.0008-.0020	0015-.0040	0020-.0060	0030-.0090


Tool Steels <30 RC (4140, 4340, A2, D2, O1, S7, P2,H13)				
SFM	Chipload Per Tooth			
<u>2, 3, &amp; 4 Flute</u>	<u>up to .125 dia.</u>	<u>.125-.250 dia.</u>	<u>.250-.500 dia.</u>	<u>.500-1.0 dia.</u>
150-225	.0005-.0010	0008-.0020	0010-.0030	0020-.0040

Carbon Steels <35 RC (A36, 1000's, 1100's, 1300's)				
SFM	Chipload Per Tooth			
<u>2, 3, &amp; 4 Flute</u>	<u>up to .125 dia.</u>	<u>.125-.250 dia.</u>	<u>.250-.500 dia.</u>	<u>.500-1.0 dia.</u>
175-250	.0006-.0015	0010-.0025	0015-.0040	0020-.0050


- <http://www.custompartnet.com/calculator/milling-speed-and-feed>



# VIBRATION (CHATTER)




# VIBRATION



**Static chip thickness**


**- Vibration at present tooth period**

**+ Vibration at previous tooth period**



# VIBRATION

- For Max Material Removal Rate:
  - Choose highest spindle RPM
  - Tune tool length to stay in a stable lobe at top spindle RPM



# VIBRATION

## Stability Lobes for Bull Nose Cutter and Al7075

