

# Vertical Milling

---




# Doing Vertical Milling

---

- Select stock
  - material, dimension
- Select workholding
  - usually vise or strap clamps
- Select tools & create toolpath
  - Esprit, Fusion360, Inventor HSM or hand-edited G-code for CNC, by hand for manual
- Set work and tool offsets (for CNC)
- Determine feeds, speeds, and cutting depth
  - CAM tools help with this for CNC (Esprit, HSM Works, Fusion360)

# Coordinate System

---





# Work Offsets


---

- G54-G59
- Different offsets will be identified for different vise jaw corners.
- If Z0 is top of stock, measure from table and subtract 600.0mm.
- Work probe should be available soon.




# Offsets

---







# Setting Work Offset



# Tool Offsets



- Enter tool data in offset table
- Put tool in spindle
- Indicate tool number in TOOL REGISTRATION screen





# Tool Offsets

- Run program 00002, move tool close to sensor, press START again.





# Process

---

- Rigidity:
  - use shortest tool and tool holder
    - deflection of tool or work causes *form* error
  - keep workpiece firmly clamped and supported
  - avoid speed/feed/depth combos that chatter
- Heat:
  - use carbide tools when heat is a problem
  - keep chips cleared (liquid or air coolant)
    - hard chips get harder
    - soft chips stick to tool
  - don't go too fast OR too slow
- Chip load:
  - keep volume removed constant!
  - especially watch tool entry, exit, corners

# Setting Feeds & Speeds

---

<u>Aluminum (6061, 2024, 7075)</u>				
SFM	Chipload Per Tooth			
<u>2, 3, &amp; 4 Flute</u>	<u>up to .125 dia.</u>	<u>.125-.250 dia.</u>	<u>.250-.500 dia.</u>	<u>.500-1.0 dia.</u>
300-500	.0008-.0020	0015-.0040	0020-.0060	0030-.0090

<u>Tool Steels &lt;30 RC (4140, 4340, A2, D2, O1, S7, P2,H13)</u>				
SFM	Chipload Per Tooth			
<u>2, 3, &amp; 4 Flute</u>	<u>up to .125 dia.</u>	<u>.125-.250 dia.</u>	<u>.250-.500 dia.</u>	<u>.500-1.0 dia.</u>
150-225	.0005-.0010	0008-.0020	0010-.0030	0020-.0040


<u>Carbon Steels &lt;35 RC (A36, 1000's, 1100's, 1300's)</u>				
SFM	Chipload Per Tooth			
<u>2, 3, &amp; 4 Flute</u>	<u>up to .125 dia.</u>	<u>.125-.250 dia.</u>	<u>.250-.500 dia.</u>	<u>.500-1.0 dia.</u>
175-250	.0006-.0015	0010-.0025	0015-.0040	0020-.0050

- <http://www.custompartnet.com/calculator/milling-speed-and-feed>




# Vibration

---



# Vibration


- For Max Material Removal Rate:
  - Choose highest spindle RPM
  - Tune tool length to stay in a stable lobe at top spindle RPM





# Vibration

## Stability Lobes for Bull Nose Cutter and Al7075



# Example Program

---

%	(DRILL 6.35MM HOLES)
00010 (SIMPLE EXAMPLE FOR NVX)	
(OP1- TOP SIDE)	G28 Z0
(STOCK- 50MM X 40MM X 50MM)	T9 M6
(G54 ZERO- LEFT FRONT TOP)	G43 H9
G54	S2000 M3
G00 G40 G90 G17 G21	M8
(SPOT DRILL HOLES)	G0 X12.5 Y12.5 Z2.5
T7 M6	G83 Z-2.5 Q2.5 R2.5 F250.0; (CANNED DRILL CYCLE)
G43 H7	X12.5 Y25.0
S2000 M3	X25.0 Y25.0
M8	X25.0 Y12.5
G0 X12.5 Y12.5 Z2.5	
G81 Z-2.5 R2.5 F250.0; (CANNED DRILL CYCLE)	G80 G0 Z2.5; (CANCEL CANNED CYCLE)
X12.5 Y25.0	
X25.0 Y25.0	M9
X25.0 Y12.5	M5
G80 G0 Z2.5; (CANCEL CANNED CYCLE)	
M9	G28 Z0
M5	M30
	%



# G-Codes for Milling

---

G00	Rapid positioning
G01	Linear interpolation (feeding)
G02	CW Circular interpolation
G03	CCW Circular interpolation
G04	Dwell
G21	Metric system
G30	Return to reference point
G40	Cancel tool radius compensation

# G-Codes for Milling

---

G54-G59	Select work coord system
G65	Macro call
G81	Drill canned cycle
G83	Peck drill canned cycle
G84	Tapping canned cycle
G90	Absolute coordinates
G91	Incremental coordinates



# M-Codes for Milling

---

M0	Program Stop
M1	Opt. Program Stop
M3	Start spindle (normal rotation)
M4	Start spindle (reverse rotation)
M5	Stop spindle
M6	Tool change
M8	Start coolant