ENGR480 Manufacturing Systems


MWF 11:00 CSP165


Lab Tues 2-5PM KRH105

Schedule and Information at https://engr.wallawalla.edu/engr480

Assignments and dropboxes at D2L

Factory Automation







Past Projects

Wooden puzzles

Brushless motor stators

Flashlights

Yoyos

Blending plastic pellets

Winding filament on spools

Intellipaper testing

Cell phone cases

Headlamps

Glass/steel nozzles

Mosaics

Syringe swapping

Mandrel / Glass tube assembly

Glass vial fill & finish

Automation Project

Rejuvenating Dry Erase Markers





Refilling

http://sds.staples.com/msds/805690.pdf

3. COMPOSITION/INFORMATION ON INGREDIENTS

3.2 Mixtures

Hazardous components

Component		Classification	Concentration
Ethanol			
CAS-No. EC-No. Index-No.	64-17-5 200-578-6 603-002-00-5	Flam. Liq. 2; H225	50 - 70 %
2-Propanol		·	
CAS-No.	67-63-0	Flam. Liq. 2; Eye Irrit. 2A;	10 - 20 %
EC-No.	200-661-7	STOT SÉ 3; H225, H319,	
Index-No.	603-117-00-0	H336	

For the full text of the H-Statements mentioned in this Section, see Section 16.

https://www.officedepot.com/pdf/msds/259251.pdf

Section Three:	Composition	

Solvents

- Isopropyl Alcohol (2-Propanol)
- Ethyl Alcohol (Ethanol)
- Acetone

Safety

Hazard statement(s) H225 H319 H336	Highly flammable liquid and vapor. Causes serious eye irritation. May cause drowsiness or dizziness.
Precautionary statement(s)	
P210	Keep away from heat/ sparks/ open flames/ hot surfaces. No smoking.
P233	Keep container tightly closed.
P240	Ground/bond container and receiving equipment.
P241	Use explosion-proof electrical/ ventilating/ lighting/ equipment.
P242	Use only non-sparking tools.
P243	Take precautionary measures against static discharge.
P261	Avoid breathing dust/ fume/ gas/ mist/ vapors/ spray.
P264	Wash skin thoroughly after handling.
P271	Use only outdoors or in a well-ventilated area.
P280	Wear protective gloves/ eye protection/ face protection.
P303 + P361 + P353	IF ON SKIN (or hair): Take off immediately all contaminated
	clothing. Rinse skin with water/ shower.
P304 + P340 + P312	IF INHALED: Remove person to fresh air and keep comfortable for breathing. Call a POISON CENTER/ doctor if you feel unwell.
P305 + P351 + P338	IF IN EYES: Rinse cautiously with water for several minutes.
	Remove contact lenses, if present and easy to do. Continue
	rinsing.
P337 + P313	If eye irritation persists: Get medical advice/ attention.
P370 + P378	In case of fire: Use dry sand, dry chemical or alcohol-resistant foam to extinguish.
P403 + P233	Store in a well-ventilated place. Keep container tightly closed.
P403 + P235	Store in a well-ventilated place. Keep cool.
P405	Store locked up.
P501	Dispose of contents/ container to an approved waste disposal

First Assignment

1. Look for email from Catme.org, follow link, and take Team Making survey

2. From a campus computer or vpn, go to:

https://elock.cs.wallawalla.edu and set up your account so I can give you access to KRH105

3. Do internet research on refilling dry erase markers.